



**Material Safety Data Sheet**  
 Golden West  
 Throttle Body, Choke Carburetor Cleaner

<b>Material Safety Data Sheet</b> May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.	U.S. Department of Labor Occupational Safety and Health Administration (Non-Mandatory Form) Form Approved OMB No. 1218-0072
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------

Identity (As Used on Label and List) Golden West Synthetic Gear Oil 75W90	Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.
------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------

**Section I**

Manufacturer's Name Golden West Packaging Co.	Emergency Telephone Number 210-649-1401
Address (Number, street, city, state and ZIP code) 13598 Hwy 87 East Adkins, TX 78101	Telephone Number for Information 210-649-1401
	Date Prepared 2007
	Signature of Preparer (optional)

**Section II - Hazardous Ingredients/Identity Information**

Components - Chemical names and common names (Hazardous Components 1% or greater, Carcinogens 0.1% or greater)	CAS Number	SARA III List	OSHA PEL (ppm)	ACGIH TLV (ppm)	Carcinogen Ref. Source
Methylene Chloride	75-09--2	Yes	25	50	a,b
Methanol	67-56-1	Yes	200 skin	200 skin	d
Toluene	108-88-3	Yes	100	50 skin	d
Carbon Dioxide (propellant)	124-38--9	No	5000	5000	d

**Section III - Physical/Chemical Characteristics**

Boiling Point - 104-232°F	Specific Gravity (H2O = 1)	0.93
Vapor Pressure - PSIG@70°F	Melting Point	N.A.
Vapor Density (AIR = 1) - Heavier than air	Evaporation Rate (Butyl Acetate = 1)	N.E.
Solubility in Water - None		
Appearance and Odor - Colorless with strong solvent odor.		

**Section IV - Fire and Explosion Hazard Data**

Flash Point (Method Used)	N.A.	Flammable Limits - Flammable	LEL - N.E.	UEL - N.E.
Extinguishing Media - Foam or dry chemical. Use water spray to cool exposed surfaces.				
Special Fire Fighting Procedures - Self contained breathing apparatus.				
Unusual Fire and Explosion Hazards - Do not expose aerosols to temperatures above 120°F or container may rupture				
Style CU-FP 174 Labelmaster, Div. Of American Labelmark Co. Inc. 60646			OSHA 174, Sept. 1985	

<b>Section V - Reactivity Data</b>				
Stability - Stable		Conditions to Avoid - Open flame, welding arcs, heat and sparks		
Incompatibility (Materials to Avoid) - Acids and strong oxidizers.				
Hazardous Decomposition or Byproducts - Includes but not limited to: smoke, fumes, carbon monoxide, carbon dioxide, hydrogen chloride, and trace amounts of phosgene and chlorine.				
Hazardous Polymerization - N.A.	May Occur	Conditions to Avoid -		
	Will Not Occur - X			
<b>Section VI - Health Hazard Data</b>				
Route(s) of Entry: Inhalation of burned product. Wash off skin.		Inhalation? Avoid	Skin? Avoid contact with skin	Ingestion? N.A.
Health Hazards (Acute and Chronic) - Avoid fumes when burned. Avoid prolonged contact with skin.				
Carcinogenicity: Possible	NTP?	IARC Monographs?	OSHA Regulated?	
Signs and Symptoms of Exposure - Irritation of eyes when in contact with fumes or smoke when burned.				
Medical Conditions Generally Aggravated by Exposure - May aggravate existing eye, skin or respiratory conditions				
Emergency First Aid Procedures - Wash skin with soap after contact.				
<b>Section VII - Precautions for Safe Handling and Use</b>				
Steps to be Taken in Case Material is Released or Spilled - Absorb spilled liquid. Do not flush to sewers or drains.				
Waste Disposal Method - According to local, state and federal law.				
Precautions to be Taken in Handling and Storing - Do not puncture or incinerate containers. Do not store at temperatures above 120°F				
Other Precautions - Keep out of reach of children. Read and follow all label directions. Remove ignition sources. Avoid breathing fumes. Avoid food contamination.				
<b>Section VIII - Control Measures</b>				
Respiratory Protection (Specify Type) - Required				
Ventilation	Local Exhaust - Required	Special -		
	Mechanical (General) -	Other -		
Protective Gloves - Recommended				
Eye Protection - Goggles				
Other Protective Clothing or Equipment - Eye wash station.				
Work/Hygienic Practices - Always wash exposed skin in soap-water solution.				
U.S.G. P.O.: 1986-491-529/45775				